



# **Sulphur Compliance & Enforcement**

It was widely anticipated that IMO 2020 would bring significant challenges as to fuel quality and compliance with the new sulphur limit for VLSFO 0.50% Wt. not least due to the initial changes required for the infrastructure and because of the changing face of blends needed to achieve these lower limits.

"Sulphur Claims are worryingly still responsible for around 1 in 3 of every offspecification notice alleged for VLSFO"

It therefore wasn't too much of a surprise when a spike of claims occurred initially, these perhaps due to cross-over or cross contamination of High Sulphur and Very Low Sulphur Fuels.

However since then, we have settled into a new normal whereby Sulphur Claims are worryingly still responsible for around 1 in 3 of every off- specification notice alleged for VLSFO.

### **Current Statistics**

Data available for the last 90 days suggests that the global average for VLSFO Sulphur Content is 0.46%Wt which on the face of it appears good news.

Globally, when comparing thousands of lines of data, 97.8% of all VLSFOs tested at or below 0.50%Wt Sulphur during this time, 1.6% tested between 0.51 and 0.53%Wt Sulphur and 0.6% tested at or above 0.54%Wt Sulphur

However when we drill into this further and consider key bunker hubs it is very noticeable how some blending hubs perform much worse than others. For example 4.1% of Rotterdam fuels test between 0.51% and 0.53% and 2.2% of VLSFO's at 0.54% or above.

Singapore on the other hand is seen to perform far better with less than 1% of all fuels testing above the 0.50% Sulphur limit which somewhat bucks the general trend that blend hubs are by far the highest risk areas for Sulphur Compliance.

### The team in this article

### Chris Turner

Manager - Bunker Quality and Claims Integr8 Fuels



P: +65 662 200 42 E: chris.t@integr8fuels.com

Port	Country	On-spec	Toleran	Off-spec
SINGAPORE	SINGAPORE	99.2	0.8	0.1
FUJAIRAH	U.A.E.	95.8	3.0	1.2
ROTTERDAM	NETHERLAN	93.7	4.1	2.2
ANTWERP	BELGIUM	94.9	3.7	1.3
ULSAN	KOREA, REP	100.0		
Grand Total		97.8	1.6	0.6

Table 1 - Levels of Non-Compliance Alleged by Port

## **Trading Intelligence**

### Research and Advisory Services Division

Issue No. 44 | 9th September 2021



Singapore's performance is because of the port average being 0.47% (see table 2 below) which coincidentally is the level of 95% confidence less the specification – in other words the 0.50% limit would only be breached one time in twenty at this level.

Even better performing, Ulsan (Korea), has a Zero Non-Compliance level because of their port average (below) of 0.44%Wt Sulphur. In other words fuels are blended well within the safety margin.

Port	Avg Test Value	Min Test Value	Max Test Value	Sample Count
FUJAIRAH	0.49	0.00	3.40	801
ANTWERP	0.49	0.03	0.83	343
ROTTERDAM	0.49	0.08	1.64	512
GIBRALTAR	0.48	0.34	0.78	373
BALBOA	0.47	0.28	0.53	377
ALGECIRAS	0.47	0.18	0.80	248
SINGAPORE	0.47	0.00	0.68	3,067
HOUSTON	0.47	0.34	0.51	230
ISTANBUL	0.47	0.00	0.54	253
LAS PALMAS	0.47	0.29	0.52	196
MALTA	0.47	0.32	0.54	235
HONG KONG	0.47	0.00	0.55	305
NEW ORLEANS	0.46	0.09	0.56	105
ZHOUSHAN	0.46	0.29	0.52	171
SHANGHAI	0.46	0.34	0.53	203
LONG BEACH	0.45	0.38	0.50	127
BUSAN	0.45	0.31	0.50	206
ULSAN	0.44	0.31	0.50	163
SANTOS	0.44	0.35	0.50	307
YOSU	0.44	0.25	0.52	121

Table 2 - Average Sulphur Content for VLSFOs last 90 Days by Port

Rotterdam and Antwerp are however blending at or close to the 0.50% limit (averaging 0.49%) hence the increased risk of noncompliance.

However drilling further into the Rotterdam data, the importance of data driven buying becomes apparent when you consider that some suppliers have no samples tested above 0.50% Sulphur and others having as many as one delivery in five testing above these limits. (see Table 3 below)

### **Trading Intelligence**

Research and Advisory Services Division

Issue No. 44 | 9th September 2021






Table 3 – Distribution of Sulphur Content by Supplier in Rotterdam

LSMGO however is seen to perform far better over the same period with 99.4% of all samples testing at or below 0.10%Wt, 0.3% testing at 0.11%Wt Sulphur and 0.3% of samples testing 0.12% or above.

We can therefore conclude that we are likely to receive four times as many notifications for Sulphur non- compliance for VLSFOs than MGOs and as a result it is essential that data driven purchasing is considered especially for VLSFOs.

### Compliance

To refresh our memories let us first clarify what constitutes a non-compliance within Marpol Annex VI when it comes to Sulphur in bunker fuels.

For VLSFO, the Marpol Sample provided by the Supplier (& listed on the BDN) cannot exceed 0.50% Wt. Sulphur and they do not benefit from the tolerance (written around 95% confidence limits) that the vessel enjoys whereby the 'In Use' or 'Onboard samples' are only non-compliant at the 0.54%Wt Sulphur level or above

Similarly for MGO, the supplier cannot exceed 0.10%Wt Sulphur but the 'in use' or 'onboard' samples are only non-compliant at 0.12%Wt Sulphur or above.

Moreover it is important to draw a clear line in the sand between the commercial samples as governed by the bunker contract and the Marpol sample placed onboard the vessel for regulatory purposes with regard their value in defining compliance (or otherwise).

Simply put, commercial samples are not defined in the Sulphur verification procedure within Appendix VI of Marpol Annex VI. Marpol Annex VI does not even mandate the testing of an owner's sample, only that a compliant BDN is placed onboard the vessel along with a Marpol Sample, this borne out by anecdotal evidence of owners requesting Sulphur is not reported on their quality reports due to the difficulties that may arise as a result.

# **Trading Intelligence**

Research and Advisory Services Division

Issue No. 44 | 9th September 2021



#### **Enforcement**

Sadly the only consistent part of enforcement by Port State Control (PSC) is their inconsistent approach to non-compliance.

"Sadly the only consistent part of enforcement by Port State Control (PSC) is their inconsistent approach to non-compliance."

Examples of concern include Authorities treating a fuel as non-compliant based on a single in use sample testing within the tolerance levels at 0.51 or 0.52% or even debunkering being demanded basis an owner test marginally above 0.50% Sulphur

This lack of clarity has been causing concern for some time but despite lobbying by IBIA within IMO we are still no closer to a consistent global approach as to the basis that PSCs determine that a fuel is non-Compliant as per Marpol Annex VI.

IBIA pushed to ensure a consistent approach to verification by implementing the amended Sulphur verification procedure (as adopted by MEPC 75) however this was rejected.

This is disappointing as these procedures cover the analysis of the Marpol sample to verify the fuel delivered to the vessel and the use of 'in use or onboard' samples to verify the fuel in use, this again incorporating 95% confidence

Therefore it remains possible that a black and white outcome still could be enforced onto a vessel despite the shades of grey basis the inherent errors of the test method itself and these concerns can only lend themselves to adjusting your buying strategies accordingly and trying to prevent these issues at source.

It is important therefore to use online platforms such as Engine where quality benchmarking gives us the best chance to navigate through this minefield and allows our customers to sail on with fair winds and calm seas.

So to conclude, whilst these inconsistencies remain it is imperative in to ensure that purchasing strategies incorporate port and supplier risk and benchmarking of suppliers and ports can save you a lot more than money, it can stop a claim spoiling your day?

#### DISCLAIMER

This article has been prepared by, and the opinions expressed are those of, Integr8 Fuels as of the date of writing (the "Materials") and are subject to change without notice. Integr8 Fuels does not undertake to update or revise the Materials. The Materials are intended to provide general and preliminary information, and is not intended to be relied upon, and must not be read, as financial, legal, business, investment, accounting, tax or other advice or guidance. The Materials are also not addressed to, and do not contemplate, the individual circumstances of any person, including without limitation its financial condition, business environment, investment knowledge and experience, objectives, investment horizon, risk tolerance and preferences. Each person must independently evaluate information contained in the Materials, and form its own opinion and/or seek professional advice, as to the course of conduct most appropriate to it.

Save for this disclaimer, the Materials are not intended to create legally binding relations. The Materials further do not constitute an offer or invitation to any person to trade with, invest in, provide finance to or take any other position with respect to Integr8 Fuels, any of its affiliates or any other person. In preparing the Materials, Integr8 Fuels has acted on its own behalf and must not be regarded as agent or representative of any other person.

The information in the Materials is given in good faith but without guarantee, and notwithstanding anything to the contrary Integr8 Fuels makes no representation as to its accuracy, completeness, authenticity or source. To the fullest extent permitted by applicable law, Integr8 Fuels shall have no liability in contract, tort (including negligence) or otherwise for any direct, includental, special, punitive or consequential damages or losses, including but not limited to loss of profits, revenue, business, opportunity, goodwill, reputation or business interruption, that result in any way from the use of content provided in the Materials.

The Materials may not be used, copied, reproduced, disseminated, quoted or referred to in any publication, presentation or other document (with or without attribution to Integr8 Fuels) at any time or in any manner without the express, prior written consent of Integr8 Fuels.

Integr8 Fuels consists of Integr8 Fuels Holding Inc of Trust Company Complex Ajeltake Road Ajeltake Island, Majuro Marshall Islands MH 96960 and all of its subsidiaries.